1. Loosen the screws on the PC cover and open it

   Open the lamp cover

   TOOL Screwdriver

2. Loosen the screws on the driver.
   Take out the LED module from the
   PC cover module.

   TOOL Screwdriver

3. Loosen the screws on the LED board

   Take out the red and black wire
   from the LED module

   Take out the blue and brown wire
   from the terminal block

   TOOL Screwdriver
   Electric soldering iron

4. Re-solder the red and black wire of the new
   driver on the LED module.

   Fix the LED board with screws
   to the lens module.

   Connect the blue and brown wire
   to the terminal block

   TOOL Screwdriver
   Electric soldering iron

5. Fix the new driver with screws.
   Attach the LED module.

   TOOL Screwdriver

6. Fix the PC cover with screws and attach
   the lamp cover

   TOOL Screwdriver