


A

loosen the hexagon screw




TOOL

wrench

B

loosen the screws




TOOL

screwdriver

C

desolder the red & black wire




TOOL

screwdriver

electric soldering  
iron

D

Resolder the red & black wire on the  
new LED board then fix it




Put some glue on the back side

TOOL

wrench

electric soldering  
iron

E



TOOL

wrench