


A

remove the hexagon screw to open the device




wrench

TOOL

B

desolder the red and black wire from the LED board
take out the blue and brown wire from the terminal block




screwdriver

electric soldering
iron

TOOL

C

change the driver, resolder the red and black wire on the LED
board, reconnect the blue and brown wire on the terminal
block



Loosen the screw

screwdriver

electric soldering
iron

TOOL

TOOL

TOOL

TOOL