


A

Loosen the screw




wrench

TOOL

B

desolder the red & black wire on the LED board, remove the blue and brown wire from the terminal block




screwdriver

electric soldering
iron

TOOL

C

resolder the red & black wire on the LED board, connect the blue and brown wire in the terminal block




screwdriver

electric soldering
iron

TOOL

Change the driver

D



screwdriver

TOOL

TOOL

TOOL

TOOL

TOOL