

A

TOOL screw driver

B

TOOL

C

TOOL screw driver

D

2. Take out the back board

1. push out the wire, do not pull it out.

TOOL

E

1. Take out the light guide and diffuser

2. Desolder the black & red wire

TOOL Electric soldering iron

F

Tear out the led strip from the housing

TOOL

G

1. Attach a new led strip
2. solder the black and red wires

TOOL Electric soldering iron

H

Put back all the light guide and diffuser in turn

TOOL

I

Push back the wire to the clamp on the back board

TOOL

G

Put back the back board and screw

TOOL screwdriver

H

Connect the driver connectors

TOOL

I

Fix the hanging board

TOOL screwdriver